



VEHICLE INSPECTION REPORT

GN68XMF

Toyota Auris 1.2T Icon Tech TSS 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2018	Body Style	Hatchback	Last service miles	50,834
Year	2018	Keys	2	MOT Due	31/08/2027
Mileage	50,979 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	7	Doors	5
VIN	SB1MA3JE70E058172	Last service date	28/08/2026		

Last Service - 28.08.2026 at 50834 miles (7 Services)

Tyres

NSF	BUDGET	3.0mm
NSR	CONTINENTAL	2.0mm
OSF	BUDGET	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Lane departure warning
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Alarm

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5




3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osf
Dented
Between 10mm + 30mm



6: Door osr
Poor Previous Repair
Poor Paint



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




11: Door nsr
Chipped
1 To 5



12: Door nsf
Poor Previous Repair
Poor Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK