



VEHICLE INSPECTION REPORT

LK13XEA

Volkswagen Tiguan 2.0 TDi BlueMotion Tech R-Line 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	04/03/2013	Keys	2	CAP Clean	£5,600.00
Year	2013	Service history	Yes	CAP Average	£4,900.00
Mileage	78,204 Miles Warranted	Service documents	Service Book	CAP Below	£4,200.00
Fuel Type	DIESEL	Number of stamps	11	Gearbox	SEMI AUTO
Colour	WHITE	Last service date	15/05/2026	Gears	7
VIN	WVGZZZ5NZDW074064	Last service miles	76,438	Doors	5
Body Style	Estate	MOT Due	18/03/2027		

Last Service - 15.05.26 at 76438 miles (11 services (7 main dealer)) Engine runs fine with rattle noise

Tyres


NSF	MICHELIN	Damaged
NSR	UNIROYAL	6.0mm
OSF	MICHELIN	Damaged
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip




5: Wheel osr
Scratched
Up To 50mm



6: Bumper Rear
Poor Previous Repair
Paint Flake



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
UpTo 25mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
UpTo 10mm



13: Roof
Rusted
Over 5mm



14: Seat Base Cover osf
Torn
Over 3mm



15: B Post os
Chipped
1 To 5



16: Wiper Rear
Missing
Replace



17: Tyre osf
Damaged
Replace



18: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK