



VEHICLE INSPECTION REPORT

RX16EFR

Toyota Yaris 1.33 VVT-i Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/04/2016	Body Style	Hatchback	Last service miles	66,121
Year	2016	Keys	2	MOT Due	13/04/2027
Mileage	68,255 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	10	Doors	5
VIN	VNKKJ3D300A353450	Last service date	30/03/2026		

Last Service - 30.03.26 @ 66121 miles (10 main dealer services)
Clutch replaced 10.09.26 @68092 miles

Tyres

NSF	FALKEN	5.0mm
NSR	LANDSAIL	5.0mm
OSF	FALKEN	5.0mm
OSR	LANDSAIL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Other
N/A
N/A
Lacquer pilling on headlight




4: Wing nsf
Chipped
1 To 5




5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: C Post ns
Dented
With Paint Damage



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Door osr
Chipped
1 To 5



12: Door osf
Chipped
Edge Chip



13: Wing osf
Chipped
1 To 5



14: A Post os
Chipped
1 To 5



15: Wheel osf
Scratched
Up To 50mm



16: Roof
Chipped
Over 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK