



VEHICLE INSPECTION REPORT

YO19MVF

Peugeot 308 1.2 PureTech 130 Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2019	Body Style	Estate	Last service miles	84,505
Year	2019	Keys	2	MOT Due	02/06/2027
Mileage	91,863 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	7	Doors	5
VIN	VF3LRHNSTKS240655	Last service date	03/06/2026		

Last Service - 03.06.2026 at 84505 miles (7 Services)

Tyres

NSF	INVOVIC	3.0mm
NSR	BUDGET	2.0mm
OSF	NEXEN	3.0mm
OSR	INVOVIC	2.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint




5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Wheel osr
Corroded
Light




12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		