



## VEHICLE INSPECTION REPORT

**GV19ZYD**

### Suzuki Swift 1.2 Dualjet SZ3 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



#### Details

|           |                        |                   |              |                    |         |
|-----------|------------------------|-------------------|--------------|--------------------|---------|
| Reg. date | 31/05/2019             | Body Style        | Hatchback    | Last service miles | 42,356  |
| Year      | 2019                   | Keys              | 2            | MOT Due            | Expired |
| Mileage   | 49,476 Miles Warranted | Service history   | Yes          | Gearbox            | MANUAL  |
| Fuel Type | PETROL                 | Service documents | Service Book | Gears              | 5       |
| Colour    | SILVER                 | Number of stamps  | 7            | Doors              | 5       |
| VIN       | JSAAZC83S00269026      | Last service date | 30/09/2025   |                    |         |

Last Service - 30.09.25 @ 42356 miles (7 main dealer services) Low clutch  
Oil light on

#### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 2.0mm |
| NSR   | BUDGET | 4.0mm |
| OSF   | BUDGET | 4.0mm |
| OSR   | BUDGET | 4.0mm |
| Spare |        |       |

## Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Air conditioning
- ABS
- Tyre pressure monitor
- Steel wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Dented  
With Paint Damage



4: Door osr  
Chipped  
1 To 5



5: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



6: Bumper Rear  
Chipped  
1 To 5



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Door nsr  
Dented  
With Paint Damage



9: Door nsf  
Dented  
With Paint Damage



10: Bumper Front  
Scratched  
25 to 100mm Thru Paint



11: Bonnet  
Chipped  
1 To 5



12: Screen Front  
Chipped  
UpTo 10mm



13: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Poor  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |       |
|--------------------------|----|------------------------------------------------|-------|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK    |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK    |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK    |
|                          |    | No Excessive Smoking                           | OK    |
| EML light illuminated    | OK | Oil warning light illuminated                  | Fault |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK    |
| ABS light illuminated    | OK |                                                |       |
| Windows                  | OK | Radio                                          | OK    |
|                          |    | Steering                                       | OK    |