



VEHICLE INSPECTION REPORT

GY70ULW

Vauxhall Astra 1.2 Turbo 145 Elite Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/10/2020	Body Style	Hatchback	Last service miles	53,793
Year	2020	Keys	1	MOT Due	Expired
Mileage	63,715 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	W0VBE6EW5LG047312	Last service date	08/09/2025		

MOT EXPIRED

LAST SERVICE 08/09/2025 @ 53,793 MILES (5 SERVICES, ALL MAIN DEALER) Eml light is on car been plugged in and detected system voltage high, active grille air shutter A performance, turbo super charger underboost
Sat nav faulty

Tyres

NSF	BUDGET	4.0mm
NSR	NEXEN	6.0mm
OSF	BUDGET	4.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Service indicator
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Cracked
UpTo 25mm




4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




6: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Dented
Between 10mm + 30mm




10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Chipped
Edge Chip



18: Door osr
Dented
2 Or Less UpTo 10mm



19: Door osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm



22: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK