



VEHICLE INSPECTION REPORT

WX69WCZ

Suzuki Swift 1.0 Boosterjet SHVS SZ5 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2019	Body Style	Hatchback	MOT Due	14/09/2027
Year	2019	Keys	2	Gearbox	MANUAL
Mileage	30,176 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Doors	5
Colour	SILVER	Number of stamps	4		
VIN	JSAAZC23S00253019	Last service date	21/09/2026		

£90 ADDITIONAL FEE

Last Service - 21.09.2026 at UNKNOWN miles (4 Services)

Tyres


NSF	FALKEN	6.0mm
NSR	BRIDGESTONE	5.0mm
OSF	FALKEN	6.0mm
OSR	WINDFORCE	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Digital radio
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Bumper Front
Insecure
Action Required



5: Other
N/A
N/A




6: Wing nsf
Dented
Over 30mm



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Sill ns
Dented
Over 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Insecure
Action Required



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Between 10mm + 30mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Chipped
Edge Chip



19: Wing osf
Poor Previous Repair
Poor Paint



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	-	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK