



VEHICLE INSPECTION REPORT

DE64OHY

Volkswagen Golf 2.0 TSI R 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2014	Body Style	Hatchback	Last service miles	56,718
Year	2014	Keys	2	MOT Due	25/02/2027
Mileage	65,252 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	10	Doors	5
VIN	WVWZZZAUZFW106826	Last service date	28/01/2025		

£90 ADDITIONAL FEE

Last Service - 28.01.25 @ 56718 miles (10 services)

Sticky clutch

Tyres


NSF	ROADSTONE	Damaged
NSR	ROADSTONE	Damaged
OSF	ROADSTONE	Damaged
OSR	BRIDGESTONE	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Tyre osf
Damaged
Replace



2: Tyre nsf
Damaged
Replace




3: Tyre nsr
Damaged
Replace




4: Bonnet
Chipped
1 To 5




5: Bumper Front
Poor Previous Repair
Paint Flake




6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5



8: Door nsf
Chipped
1 To 5




9: Door nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm




11: Qtr Panel nsr
Dented
With Paint Damage




12: Bumper Rear
Scratched
25 to 100mm Thru Paint




13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Chipped
1 To 5



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
Between 10mm + 30mm




17: Door osf
Chipped
Edge Chip



18: Door osf
Chipped
1 To 5



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
Over 10mm



22: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK