



VEHICLE INSPECTION REPORT

GU15PUX

Volvo XC60 D4 [181] SE Lux Nav 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	27/03/2015	Body Style	Estate	Last service miles	63,279
Year	2015	Keys	2	MOT Due	26/03/2027
Mileage	100,084 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	8
Colour	SILVER	Number of stamps	9	Doors	5
VIN	YV1DZ73CDF2741852	Last service date	17/03/2023		

£90 ADDITIONAL FEE

Last Service - 17.03.2023 at 63279 miles (9 Services)

Tyres


NSF	MAXXIS	6.0mm
NSR	TRIANGLE	6.0mm
OSF	MAXXIS	6.0mm
OSR	TRIANGLE	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Central locking

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
2 Or Less UpTo 10mm



3: Door osf
Chipped
1 To 5




4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osr
Chipped
Edge Chip



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Door nsr
Chipped
1 To 5



13: Door nsf
Dented
2 Or Less UpTo 10mm



14: Door nsf
Chipped
1 To 5



15: Wing nsf
Scratched
Over 25mm Thru Paint



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Scratched
25 to 100mm Thru Paint



18: Bumper Front
Chipped
Multiple Chips



19: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK