



VEHICLE INSPECTION REPORT

VU68ANR

Vauxhall Grandland X 1.2 Turbo SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/09/2018	Body Style	Hatchback	Last service miles	57,542
Year	2018	Keys	2	MOT Due	13/11/2026
Mileage	72,080 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	2	Doors	5
VIN	W0VZRHNY3JS202742	Last service date	29/09/2025		

£100 ADDITIONAL FEE

LAST SERVICE 29/09/2025 @ 57,542 MILES (2 SERVICES)

Car shake while idle

Tyres

NSF	HANKOOK	4.0mm
NSR	KORMORAN	Damaged
OSF	HANKOOK	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Cloth seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door Pad osf
Scuffed
Over 25mm



2: Tyre nsr
Damaged
Replace



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: A Post ns
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Corroded
Light



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Chipped
1 To 5



15: Qtr Panel osr
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Chipped
1 To 5



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
With Paint Damage



19: Door osf
Dented
Between 10mm + 30mm



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wheel of
Scratched
Over 50mm



22: Wing of
Chipped
1 To 5



23: Screen Front
Chipped
Up To 10mm



24: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK