



VEHICLE INSPECTION REPORT

GV70EXO

Kia Sportage 1.6 CRDi 48V ISG GT-Line S 5dr DCT Auto [AWD]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/11/2020	Body Style	Estate	Last service miles	71,865
Year	2020	Keys	2	MOT Due	30/01/2027
Mileage	100,919 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	5	Doors	5
VIN	U5YPK812WML951128	Last service date	23/09/2024		

£100 ADDITIONAL FEE

Last Service - 23.09.24 at 71865 miles (5 main dealer services)

Emil light is on car been plugged in and detected cylinder 1- injection restricted

Cylinder 3 - injector restricted, particulate trap efficiency below threshold (bank 2)

Tyres



NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Bumper Front
Poor Previous Repair
Paint Flake



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Door osr
Chipped
1 To 5



10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Over 50mm



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		