



VEHICLE INSPECTION REPORT

GJ18AXN

Skoda Kodiaq 2.0 TDI SE 4x4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/03/2018	Body Style	Estate	Last service miles	75,119
Year	2018	Keys	2	MOT Due	10/01/2027
Mileage	82,552 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	9	Doors	5
VIN	TMBMJ7NS4H8029614	Last service date	13/09/2025		

£90 ADDITIONAL FEE
LAST SERVICE 13/09/2025 @ 75,119 MILES (9 SERVICES)

Tyres

NSF	RAPID	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	3.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
1 To 5




4: A Post ns
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
1 To 5



8: Door nsr
Poor Previous Repair
Rippled UpTo 30%



9: Wheel nsr
Scratched
Up To 50mm



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Qtr Panel nsr
Chipped
1 To 5




12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Dented
Between 10mm + 30mm




14: Door osr
Chipped
1 To 5



15: Door osf
Scratched
Over 25mm Thru Paint




16: A Post os
Chipped
1 To 5



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




18: Wing osf
Chipped
1 To 5



19: Screen Front
Scratched
Over 30mm



20: Roof
Chipped
1 To 5



21: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



22: Bumper Rear
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK