



VEHICLE INSPECTION REPORT

FV14UHK

Nissan Note 1.2 DiG-S Tekna 5dr [Style Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/07/2014	Body Style	MPV	Last service miles	104,353
Year	2014	Keys	2	MOT Due	23/02/2027
Mileage	108,451 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	10	Doors	5
VIN	SJNTBAE12U1078009	Last service date	04/03/2026		

LAST SERVICE 04/03/2026 @ 104,353 MILES (10 SERVICES) Rattling exhaust
Boot will not open

Tyres

NSF	TRIANGLE	3.0mm
NSR	BUDGET	4.0mm
OSF	TRIANGLE	3.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Park assist camera
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Dented
With Paint Damage



11: Bumper Rear
Insecure
Action Required



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm




15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
With Paint Damage



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5



19: Roof
Scratched
Over 25mm Thru Paint



20: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK