



# VEHICLE INSPECTION REPORT

**GU14XEN**

## Kia Venga 1.4 EcoDynamics 1 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                            |                   |              |                    |         |
|-----------|----------------------------|-------------------|--------------|--------------------|---------|
| Reg. date | 07/04/2014                 | Body Style        | Hatchback    | Last service miles | 90,198  |
| Year      | 2014                       | Keys              | 2            | MOT Due            | Expired |
| Mileage   | 110,863 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL  |
| Fuel Type | PETROL                     | Service documents | Service Book | Gears              | 5       |
| Colour    | SILVER                     | Number of stamps  | 5            | Doors              | 5       |
| VIN       | U5YEG811LDL066563          | Last service date | 02/07/2024   |                    |         |

£100 ADDITIONAL FEE

MOT EXPIRED

LAST SERVICE 02/07/2024 @ 90,198 MILES (5 SERVICES) Steering knocking

Traction light on

Esp light on

### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 4.0mm |
| NSR   | BUDGET | 4.0mm |
| OSF   | BUDGET | 4.0mm |
| OSR   | BUDGET | 4.0mm |
| Spare |        |       |

## Features


- Rear wiper
- Front electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Metallic Paint
- Traction control
- Steel wheels
- Electric door mirrors
- ABS
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Wing osf  
Poor Previous Repair  
Poor Paint



2: Door osf  
Poor Previous Repair  
Poor Paint



3: Door osr  
Dented  
Over 30mm



4: Qtr Panel osr  
Chipped  
1 To 5




5: Bumper Rear  
Scratched  
Over 100mm Thru Paint



6: Tailgate  
Scratched  
UpTo 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Door nsr  
Scratched  
UpTo 25mm Thru Paint




9: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



10: Wing nsf  
Chipped  
1 To 5



11: Bumper Front  
Scratched  
Over 100mm Thru Paint



12: Roof  
Rusted  
Over 5mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|               |    |                                                |    |
|---------------|----|------------------------------------------------|----|
| Engine Runs   | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes        | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
|               |    | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated    | OK |                                     |    |
| Windows                  | OK | Radio                               | OK |
|                          |    | Steering                            | OK |