



VEHICLE INSPECTION REPORT

NU59MXY

Jaguar XF 3.0d V6 Premium Luxury 4dr Auto

Cat: C
Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date 29/01/2010

Year 2010

Mileage 79,517 Miles
Warranted

Fuel Type DIESEL

Colour RED

VIN SAJAC0640ANR73729

Body Style Saloon

Keys 1

Service history None

MOT Due 21/07/2027

Gearbox AUTOMATIC

Gears 6

Doors 4

£90 ADDITIONAL FEE

Category C Insurance Loss. Vehicle Extensively Damaged But Repairable -Insurer Decided Not To Repair

NO SERVICE HISTORY

Water in a fuel message displayed

Tyres

NSF GENERAL TIRE Damaged

NSR GOODYEAR Damaged

OSF INVOVIC 6.0mm

OSR GOODYEAR Damaged

Spare

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Digital radio
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Body coloured bumpers
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos







Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Grill
Broken
Replace



4: Bumper Front
Poor Previous Repair
Paint Flake



5: Bumper Front
Insecure
Action Required



6: Wing nsf
Dented
Over 30% Of Panel



7: Wheel nsf
Scratched
Over 50mm




8: Sill Panel Trim ns
Broken
Replace



9: Handle Outer nsf
Broken
Replace




10: Door nsf
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Bumper Rear
Scratched
25 to 100mm Thru Paint




15: Boot Lid
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Chipped
1 To 5



22: Roof
Scratched
Over 25mm Thru Paint



23: Tyre nsf
Damaged
Replace



24: Tyre osr
Damaged
Replace



25: Tyre nsr
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK