



VEHICLE INSPECTION REPORT

LP62GVD

Honda CR-V 2.0 i-VTEC EX 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/01/2013	Body Style	Estate	Last service miles	44,383
Year	2013	Keys	2	MOT Due	02/10/2027
Mileage	51,763 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	BROWN	Number of stamps	1	Doors	5
VIN	SHSRE5890DU000918	Last service date	11/09/2024		

£100 ADDITIONAL FEE

Last Service - 11.09.24 @ 44383 miles (1 service)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BUDGET	5.0mm
OSF	RAPID	7.0mm
OSR	BUDGET	5.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Fixed panoramic glass roof
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos



Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace




2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Door nsr
Chipped
1 To 5




7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm




9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm




10: Bumper Rear Moulding
Broken
Replace



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Roof
Dented
Between 10mm + 30mm




13: Wheel osf
Scratched
Up To 50mm



14: Door osr
Chipped
1 To 5



15: Door osf
Chipped
Edge Chip



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Up To 50mm



19: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK