



VEHICLE INSPECTION REPORT

GU16TPF

Audi A3 1.4 TFSI 125 Sport 5dr [Nav]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/03/2016	Keys	2	CAP Clean	£5,650.00
Year	2016	Service history	Yes	CAP Average	£4,875.00
Mileage	62,276 Miles Warranted	Service documents	Printout	CAP Below	£4,125.00
Fuel Type	PETROL	Number of stamps	4	Gearbox	MANUAL
Colour	SILVER	Last service date	08/03/2021	Gears	6
VIN	WAUZZZ8V4GA129166	Last service miles	19,879	Doors	5
Body Style	Hatchback	MOT Due	31/03/2027		

£90 ADDITIONAL FEE

LAST SERVICE 08/03/2021 @ 19,879 MILES (4 SERVICES)

Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsr
Chipped
1 To 5



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Tailgate
Scratched
UpTo 25mm Thru Paint




9: Bumper Rear
Hole
Over 25mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
With Paint Damage



13: Roof
Dented
Between 10mm + 30mm



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
Edge Chip



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK