



VEHICLE INSPECTION REPORT

VK19VXA

Seat Tarraco 2.0 EcoTSI Xcellence First Ed Plus 5dr DSG 4Drive

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/03/2019	Body Style	Estate	Last service miles	87,470
Year	2019	Keys	2	MOT Due	18/04/2027
Mileage	97,087 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	9	Doors	5
VIN	VSSZZZKNZKW004706	Last service date	14/04/2026		

LAST SERVICE 14/04/2026 @ 87,470 MILES (9 SERVICES)

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Chipped
1 To 5



4: A Post ns
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Dented
Between 10mm + 30mm



8: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsr
Poor Previous Repair
Poor Paint



10: Door nsr
Dented
2 Or Less UpTo 10mm



11: Wheel nsr
Scratched
Over 50mm




12: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



13: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



14: Bumper Rear Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
Edge Chip



17: Door osf
Chipped
Edge Chip



18: Door osf
Dented
Between 10mm + 30mm



19: Wheel osf
Scratched
Over 50mm



20: Roof
Chipped
Edge Chip



21: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		