



VEHICLE INSPECTION REPORT

BU68XGS

Toyota Auris 1.8 Hybrid Icon Tech TSS 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/09/2018	Body Style	Hatchback	MOT Due	09/09/2027
Year	2018	Keys	1	Gearbox	CVT
Mileage	69,598 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Doors	5
Colour	WHITE	Number of stamps	4		
VIN	SB1MS3JE30E450319	Last service date	16/08/2023		

Last Service - 16.08.23 @ unknown miles (4 services)


Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Fascia Trim
Missing
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
With Paint Damage



7: Sill ns
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Cracked
Over 25mm



12: Bumper Reflector osr
Broken
Replace



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
UpTo 25mm Thru Paint



17: Door osf
Rusted
Over 5mm



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK