



VEHICLE INSPECTION REPORT

MT18JPV

Citroen Grand C4 Picasso 1.6 BlueHDi Flair 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/06/2018	Body Style	MPV	MOT Due	20/02/2027
Year	2018	Keys	2	Gearbox	MANUAL
Mileage	103,598 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	DIESEL	Service documents	Service Book	Doors	5
Colour	GREY	Number of stamps	6		
VIN	VF73ABHZMJJ550797	Last service date	27/07/2026		

£90 ADDITIONAL FEE
LAST SERVICE 27/07/2026 @ UNKNOWN MILES (6 SERVICES)

Tyres


NSF	BUDGET	5.0mm
NSR	FARROAD	5.0mm
OSF	BUDGET	5.0mm
OSR	FARROAD	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear armrest
- Metallic Paint
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Wheel nsf
Scratched
Over 50mm



3: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Rusted
Over 5mm



7: Wheel nsr
Corroded
Light



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: B Post ns
Dented
Between 10mm + 30mm



10: Wheel osr
Corroded
Light



11: Qtr Panel osr
Chipped
Edge Chip



12: Door osf
Chipped
Edge Chip



13: Wing nsf
Dented
Between 10mm + 30mm



14: Wing osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm



16: Bumper Front
Scratched
25 to 100mm Thru Paint



17: Screen Front
Chipped
UpTo 10mm



18: B Post os
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK