



VEHICLE INSPECTION REPORT

DG60HDH

Volkswagen Tiguan 2.0 TDi Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/09/2010	Body Style	Estate	Last service miles	86,951
Year	2010	Keys	2	MOT Due	23/04/2027
Mileage	108,415 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	DIESEL	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	13	Doors	5
VIN	WVGZZZ5NZBW016880	Last service date	01/08/2024		

£100 ADDITIONAL FEE

Last Service - 01.08.2024 at 86951 miles (13 Services)

Timing Belt Replaced 27.03.2026 @ 103382 miles Sunroof curtain broken

Roof lining sagged

Slight rattle from engine on idle

Tyres

NSF	LAUFENN	3.0mm
NSR	LAUFENN	3.0mm
OSF	LAUFENN	3.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos




1: Wing of
Dented
With Paint Damage



2: Wheel of
Scratched
Up To 50mm



3: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint




5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Dented
Between 10mm + 30mm



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Bumper Rear Moulding
Broken
Replace



9: Door nsr
Dented
With Paint Damage




10: Door Moulding nsf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Bumper Front
Poor Previous Repair
Poor Paint



13: Bumper Front Moulding
Broken
Replace



14: Bonnet
Chipped
1 To 5



15: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK