



VEHICLE INSPECTION REPORT

AF57ZDD

Land Rover Discovery 2.7 Td V6 SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2007	Keys	2	CAP Clean	£2,225.00
Year	2007	Service history	Yes	CAP Average	£1,800.00
Mileage	127,812 Miles Warranted	Service documents	Service Book	CAP Below	£1,350.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	23/11/2017	Gears	6
VIN	SALLAAA137A423118	Last service miles	105,873		
Body Style	Estate	MOT Due	19/04/2026		

£100 ADDITIONAL FEE Last service 23/11/2017 @ 105873 miles (7 SERVICES) Rattle from engine and front suspension fault

Tyres

NSF	BUDGET	Worn
NSR	BUDGET	Worn
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
Between 10mm + 30mm




4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Over 50mm

No Image

11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Dented
2 Or Less UpTo 10mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
With Paint Damage



16: Roof
Dented
Between 10mm + 30mm




17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint




19: Wing osf
Scratched
Over 25mm Thru Paint




20: Screen Front
Chipped
UpTo 10mm



21: Wheel osf
Scratched
Over 50mm



22: Tyre nsf
Worn
Replace



23: Tyre nsr
Worn
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK