



VEHICLE INSPECTION REPORT

BD64VYC

Peugeot 5008 1.6 HDi Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/11/2014	Body Style	MPV	MOT Due	02/10/2025
Year	2014	Keys	1	CAP Clean	£2,550.00
Mileage	82,300 Miles Warranted	Service history	Yes	CAP Average	£2,125.00
Fuel Type	Diesel	Number of stamps	2	CAP Below	£1,675.00
Colour	WHITE	Last service date	27/09/2024	Gearbox	MANUAL
VIN	VF30E9HD8ES087501	Last service miles	76,122	Gears	6

£65 ADDITIONAL FEE SERVICES CONFIRMED BY KAP AUTO PANELS LTD Last service 27/09/2024 @ 76122 miles (2 MAIN DEALER SERVICES) Car judders on idle
Release bearing noisy
Engine slightly knocking
Intermittent starter motor fault

Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Cruise control
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bumper Front Grill
Broken
Replace



3: Bonnet
Chipped
1 To 5



4: Wheel osf
Scratched
Up To 50mm



5: Wing osf
Chipped
1 To 5



6: Door osf
Chipped
1 To 5



7: Door osr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



9: Wheel osr
Scratched
Over 50mm




10: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



11: Boot Lid
Dented
Over 30mm



12: Qtr Panel nsr
Chipped
1 To 5



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Wheel nsr
Scratched
Over 50mm



15: Door nsr
Dented
Over 30mm



16: Door nsf
Dented
Over 2 UpTo 10mm



17: Door nsf
Scratched
Over 25mm Not Thru Paint



18: Wheel nsf
Scratched
Over 50mm



19: Wing nsf
Scratched
Over 25mm Not Thru Paint



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK