



VEHICLE INSPECTION REPORT

SC66XCE

Dacia Sandero 1.2 16V 75 Ambiance 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/12/2016	Keys	2	CAP Clean	£2,250.00
Year	2016	Service history	Yes	CAP Average	£1,800.00
Mileage	29,077 Miles Warranted	Service documents	Service Book	CAP Below	£1,375.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	RED	Last service date	18/12/2019	Gears	5
VIN	UU15SDE3355720909	Last service miles	5,564	Doors	5
Body Style	Hatchback	MOT Due	28/12/2025		

Last Service - 18.12.2019 at 5564 miles (3 services) Entertainment screen very faint

Tyres

NSF	BUDGET	Worn
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Steel wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Central locking
- Audio remote control
- Air conditioning
- Rear headrests
- Drivers airbag
- Remote central locking

Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Dented
Over 30mm



5: Door nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
With Paint Damage



8: Sill ns
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Boot Lid
Dented
Over 30mm



12: Qtr Panel osr
Dented
Over 30mm



13: Door osr
Dented
With Paint Damage



14: Door osf
Dented
Over 2 UpTo 10mm

No Image



15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Wing osf
Chipped
1 To 5

No Image

No Image

17: Tyre nsf
Worn
Replace

18: Tyre nsf
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK