

## **VEHICLE INSPECTION REPORT**

LR69KGZ

### DS Ds 3 1.2 PureTech 130 Performance Line 5dr EAT8

Inspection		Vehicle			nama
Serious Damage? No		VAT	Margin		2 CRADE
		V5	Present		
Details					
Reg. date	24/09/2019	Body Style	MPV	Last service miles	11,291
Year	2019	Keys	2	MOT Due	Expired
Mileage	22,149 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	8
Colour	WHITE	Number of stamps	4		
VIN	VR1URHNSSKW097152	Last service date	20/09/2024		

£100 ADDITIONAL FEE. Last Service: 20/09/2024 at 11291 miles. (4 main dealer services)

Ty	res	
----	-----	--

NSF	MICHELIN	4.0mm	
NSR	BUDGET	5.0mm	
OSF	BRIDGESTONE	4.0mm	
OSR	MICHELIN	4.0mm	
Spare			

### **Features**

- Bluetooth connection
- Telephone
- Air conditioning Rear electric windows
- Drivers airbag
- Central locking
- · Alloy wheels

- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- · Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- · Cloth seat trim
- Rear wiper
- Electric door mirrors Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

### **Photos**













**Eastbourne Car Auctions** 










## **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint

# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Up To 50mm

# No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Chipped 1 To 5



7: Door nsr Chipped 1 To 5

# No Image

8: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



9: Bumper Rear Scratched 25 to 100mm Thru Paint

## No Image

10: Bumper RearScratchedOver 25mm Not Thru Paint

# No Image

11: Qtr Panel osr Scratched Over 25mm Not Thru Paint



12: Door osrScratchedOver 25mm Not Thru Paint

## No Image

13: Door osf Scratched Over 25mm Not Thru Paint

# No Image

14: Wing osfScratchedOver 25mm Not Thru Paint



15: Wheel osf Scratched Over 50mm

### Interior

Carpet ConditionOKUpholstery ConditionOKSeat ConditionOKOdourNo

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake Oh		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
EME light hidrimated	UK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
			- " "
Sat nav	OK	Steering	OK