



# VEHICLE INSPECTION REPORT

**YH59DNV**

## BMW 3 Series 325d M Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/10/2009	Colour	BLACK	MOT Due	Expired
Year	2009	VIN	WBAUX52010A389228	Gearbox	AUTOMATIC
Mileage	73,656 Miles Warranted	Body Style	Estate	Gears	6
Fuel Type	Diesel	Keys	2		

Eml on


### Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Over 5mm



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Up To 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Chipped  
1 To 5

No Image




7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm




10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




14: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



15: Wheel osr  
Scratched  
Over 50mm




16: Door osr  
Chipped  
1 To 5




17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Chipped  
1 To 5



19: Door osf  
Scratched  
Over 25mm Not Thru Paint



20: Wing osf  
Scratched  
Over 25mm Not Thru Paint





21: Wheel of  
Scratched  
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK