



VEHICLE INSPECTION REPORT

LY14FPE

Vauxhall Zafira 1.8i [120] Exclusiv 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |



Details

| | | | | | |
|------------|---------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 25/06/2014 | Keys | 2 | CAP Clean | £1,675.00 |
| Year | 2014 | Service history | Yes | CAP Average | £1,300.00 |
| Mileage | 82,568 Miles Warranted | Service documents | Service Book | CAP Below | £900.00 |
| Fuel Type | Petrol | Number of stamps | 8 | Gearbox | MANUAL |
| Colour | BLUE | Last service date | 22/08/2024 | Gears | 5 |
| VIN | W0LOAHM75E2081942 | Last service miles | 77,566 | | |
| Body Style | MPV | MOT Due | 04/02/2026 | | |

Last Service - 22.08.2024 at 77566 miles (8 services) CLUTCH HIGH, HEATER STUCK ON HOT

Tyres

| | | |
|-------|---------|-------|
| NSF | BUDGET | 3.0mm |
| NSR | BUDGET | 3.0mm |
| OSF | BUDGET | 3.0mm |
| OSR | MATADOR | 4.0mm |
| Spare | | |

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Chipped
1 To 5



10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Boot Lid
Chipped
1 To 5

No Image

15: Boot Lid
Scratched
Over 25mm Not Thru Paint



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint

No Image

17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Over 50mm




19: Door osr
Chipped
1 To 5

No Image

20: Door osr
Scratched
Over 25mm Not Thru Paint



21: Door osf
Dented
Over 2 UpTo 10mm



22: Door osf
Scratched
Over 25mm Not Thru Paint



23: Wing osf
Chipped
1 To 5



24: Wing osf
Scratched
Over 25mm Not Thru Paint



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |