



VEHICLE INSPECTION REPORT

LG17EYW

Ford Mondeo 1.5 TDCi EConetic Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present



Details

Reg. date	15/03/2017	Keys	2	CAP Average	£3,250.00
Year	2017	Service history	Yes	CAP Below	£2,700.00
Mileage	113,477 Miles Warranted	Number of stamps	5	Gearbox	MANUAL
Fuel Type	Diesel	Last service date	07/08/2023	Gears	6
Colour	BLUE	Last service miles	91,432	Doors	5
VIN	WF0EXXWPCEHU18378	MOT Due	07/02/2026		
Body Style	Hatchback	CAP Clean	£3,800.00		

Slight rattle at idle

Tyres

NSF	FALKEN	3.0mm
NSR	FIRESTONE	2.0mm
OSF	BUDGET	Worn
OSR	BUDGET	Worn
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Chipped
1 To 5



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm




15: Door osf
Dented
Over 2 UpTo 10mm



16: Door osr
Chipped
Edge Chip



17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Dented
With Paint Damage



20: Wheel osf
Scratched
Over 50mm




21: Screen Front
Chipped
UpTo 10mm



22: Roof
Chipped
1 To 5



23: Tyre osf
Worn
Replace



24: Tyre osr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK