

VEHICLE INSPECTION REPORT

NH06UFC

Nissan X-Trail 2.5 16v Aventura 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE.
		V5	Present		
Details					
Reg. date	23/08/2006	Keys	2	CAP Clean	£1,450.00
Year	2006	Service history	Yes	CAP Average	£1,075.00
Mileage	99,707 Miles Warranted	Service documents	Service Book	CAP Below	£675.00
		Number of stamps	16	Gearbox	AUTOMATIC
Fuel Type	Petrol	Last service date	28/08/2024	Gears	4
Colour	GREY	Last service miles	97,274		
VIN	JN1TBNT30U0124647	MOT Due	13/07/2025		
Body Style	Estate				

DRIVE BELT REPLACED 25/09/2023 Last service 28/08/2024 @ 97274 miles (16 SERVICES 2 MAIN DEALER) book + print ESP LIGHT ON TRACTION LIGHT ON

Tyres

NSF	AVON	2.0mm	
NSR	CONTINENTAL	3.0mm	
OSF	AVON	3.0mm	
OSR	CONTINENTAL	2.0mm	
Spare			

Features

- Heated front seat
- Radio/CD
 Air conditioning
- Front armrestMetallic Paint
- · Central locking
- Navigation systemBody coloured bumpersClimate control
- · Front electric windows
- ABS
- Remote central locking

- Rear parking sensor
 Electric door mirrors
 Electric sunroof
 Electrically adjustable drivers seat
 Electrically adjustable passenger
- Rear electric windowsDrivers airbagLeather seat trim

- seat
- · Rear headrests
- Traction controlAlloy wheels

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5



5: Door nsf Chipped 1 To 5



6: Door nsr Dented With Paint Damage



7: Qtr Panel nsr Dented With Paint Damage



8: Wheel nsr Scratched Over 50mm



9: Bumper Rear Scratched Over 100mm Thru Paint

No Image

10: Boot Lid Scratched Over 25mm Not Thru Paint



11: Door osrChipped1 To 5

No Image

12: Door osrScratchedOver 25mm Not Thru Paint



13: Wheel osr Scratched Over 50mm



14: Door osf Dented Over 30mm

No Image

15: Wing osf Scratched Over 25mm Not Thru Paint



16: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated Ol		Service indicator light illuminated	OK
ABS light illuminated OK			
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		