

46 Brampton Road Eastbourne BN22 9BN 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



BMW 1 Series 118i M Sport 5dr Step Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	TBC		
Details					
Reg. date	30/09/2019	Colour	RED	MOT Due	24/09/2025
Year	2019	VIN	WBA7K320907E91070	Gearbox	AUTOMATIC
Mileage	46,858 Miles	Body Style	Hatchback	Gears	7
	Warranted	Keys	2	Doors	5
Fuel Type	Petrol				
Tyres					
NSF		PIRELLI		Damaged	
NSR		CONTINENTAL		Damaged	
OSF		BUDGET		2.0mm	
OSR		CONTINENTAL		2.0mm	
Spare					

Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
 Audio remote control
 Body coloured bumpers
 Electric door mirrors
- Body coloured bumpe
 Front armrest
- Front armrest
 Rear headrests
- Drivers airbag
- Central locking
- Electric door mirrorsFront electric windows

• PAS

Solid Paint

Cruise control

- Isofix child seat anchor points
- Remote central locking
- Front parking sensorRear parking sensor
- Rear parking sensor
 Auxiliary input socket
- Auxiliary input soc
 Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- · Heated front seat
- Rear wiper
- Digital radio
- Climate controlRear electric windows
- ABS
- Traction control
- Alloy wheels

Photos












Condition Check




Damage Photos





1: Bonnet Chipped 1 To 5

2: Bumper Front Chipped Multiple Chips



No Image

3: Wheel nsf Scratched Over 50mm



5: Door Mirror Assy nsf Scratched (Painted) UpTo 25mm Not Thru Paint



6: Door nsf Chipped 1 To 5

Scratched

Over 25mm Not Thru Paint



7: Other N/A N/A



8: Door nsr Scratched Over 25mm Thru Paint



ROBE

9: Wheel nsr Scratched Over 50mm

10: Bumper Rear Scratched 25 to 100mm Thru Paint



No Image

11: Bumper Rear Scratched Over 25mm Not Thru Paint



13: Door osf Dented Between 10mm + 30mm

12: Wheel osr Scratched Over 50mm



14: Wheel osf Scratched Over 50mm

No Image

No Image

15: Tyre nsf Damaged Replace 16: Tyre nsr Damaged Replace

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition Odour

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK