

VEHICLE INSPECTION REPORT

HV04HJK

Volvo S/v40 Series D SE

	Vehicle			nama
No	VAT	Margin		GRADE
	V5	Present	_	
13/04/2004	Body Style	Saloon	Last service miles	91,948
2004	Keys	2	MOT Due	15/03/2026
93,540 Miles	Service history	Yes	Gearbox	MANUAL
Warranted	Service documents	Service Book	Gears	5
Diesel	Number of stamps	19	Doors	4
GREY	Last service date	21/05/2024		
YV1VS70924F116237				
	13/04/2004 2004 93,540 Miles Warranted Diesel GREY	No VAT V5 13/04/2004 2004 93,540 Miles Warranted Diesel GREY VAT V5 Body Style Keys Service history Service documents Number of stamps Last service date	No VAT Margin V5 Present 13/04/2004 Body Style Saloon 2004 Keys 2 93,540 Miles Service history Yes Warranted Service documents Service Book Diesel Number of stamps 19 GREY Last service date 21/05/2024	No VAT Margin V5 Present 13/04/2004 Body Style Saloon Last service miles 2004 Keys 2 MOT Due 93,540 Miles Service history Yes Gearbox Warranted Service documents Service Book Gears Diesel Number of stamps 19 Doors GREY Last service date 21/05/2024

£65 ADDITIONAL FEE Last service 21/05/2024 @ 91948 miles (19 SERVICES 2 MAIN DEALER) SERVICE LIGHT ON **ROOF LINING DROPPED**

Tyres			
NSF	FALKEN	4.0mm	
NSR	GT RADIAL	4.0mm	
OSF	GT RADIAL	3.0mm	
OSR	GT RADIAL	4.0mm	
Spare			

Features

- · Heated front seat
- Air conditioningFront electric windows
- ABS
- Remote central locking
- Radio/CD
- Climate controlRear electric windows
- Drivers airbag
- Leather seat trim
- Body coloured bumpers
 Electric door n
 Electrically adjustable drivers seat
 Rear headrests
 Metallic Paint
 Descriptions
- Passenger airbag
- Alloy wheels
- · Electric door mirrors

- · Central locking

Photos






















Condition Check



Damage Photos




1: Bonnet Poor Previous Repair Poor Paint



2: Bumper Front Scratched 25 to 100mm Thru Paint

No Image

3: Bumper Front Scratched



5: Wheel nsf Scratched Up To 50mm



7: Door nsr Dented 2 Or Less UpTo 10mm



4: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Scratched Over 25mm Thru Paint



8: Door nsr Chipped 1 To 5



9: Wheel nsr Scratched Up To 50mm



10: Qtr Panel nsr Chipped 1 To 5



11: Qtr Panel nsr Dented Between 10mm + 30mm



12: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

13: Bumper Rear Scratched Over 25mm Not Thru Paint

No Image

14: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

15: Qtr Panel osrScratchedOver 25mm Not Thru Paint



16: Wheel osr Scratched Up To 50mm



17: Door osr Poor Previous Repair Poor Paint



18: Door osf Chipped 1 To 5



19: Wing osf Chipped 1 To 5



20: Wheel osf Scratched Up To 50mm



21: Screen Front Chipped UpTo 10mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	ОК	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK