

VEHICLE INSPECTION REPORT

RO70VZK

Renault ZOE 100kW i GT Line R135 50kWh 5dr Auto Vehicle

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	28/09/2020	Keys	2	CAP Average	£6,425.00
Year	2020	Service history	Yes	CAP Below	£5,500.00
Mileage	35,378 Miles Warranted	Number of stamps	4	Gearbox	AUTOMATIC
		Last service date	13/06/2024	Gears	1
Fuel Type	Electric	Last service miles	28,670	Doors	5
Colour	BLUE	MOT Due	27/09/2025	-	
VIN	VF1AG000065885357	CAP Clean	£7,350.00		
Body Style	Hatchback		,		

Battery is owned

Tvr	es
-----	----

NSF	BUDGET	3.0mm	
NSR	NANKANG	4.0mm	
OSF	BUDGET	3.0mm	
OSR	тоуо	4.0mm	
Spare			

Features

- Bluetooth connection
- PAS
- Digital radioClimate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

- Cruise control
- Rear parking sensor Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Front parking sensorRear wiperElectric door mirrors


- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Audio remote control
- Audio remote control
 Air conditioning
 Height adjustable drivers seat
 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



5: Wheel nsf Scratched Over 50mm



4: Wing nsf Cracked Replace



6: Door nsf Chipped 1 To 5

No Image

7: Door nsf Scratched Over 25mm Not Thru Paint



8: Door nsr Dented 2 Or Less UpTo 10mm



9: Qtr Panel nsr Dented Over 30mm



10: Wheel nsrScratchedOver 50mm



11: Bumper Rear Chipped Multiple Chips



12: Qtr Panel osr Dented Between 10mm + 30mm



13: Wheel osr Scratched Over 50mm



14: Door osf Chipped 1 To 5



15: Door osf Dented Between 10mm + 30mm



16: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK		Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK