



# VEHICLE INSPECTION REPORT

**EF15YJX**

## Ford Kuga 2.0 TDCi 150 Titanium 5dr 2WD

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/06/2015	Keys	2	CAP Average	£3,075.00
Year	2015	Service history	Yes	CAP Below	£2,525.00
Mileage	99,000 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	Diesel	Number of stamps	6	Gears	6
Colour	BLACK	Last service date	19/06/2021	Doors	5
VIN	WF0AXXWPM AFL31031	Last service miles	54,312		
Body Style	Hatchback	CAP Clean	£3,600.00		

£65 ADDITIONAL FEE . EXPIRED MOT. Last service 19-06-2021 @ 54312 miles (6 MAIN DEALER SERVICES)

### Tyres


NSF	BUDGET	2.0mm
NSR	NEXEN	3.0mm
OSF	BUDGET	3.0mm
OSR	NEXEN	4.0mm
Spare		

## Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

## Photos






## Condition Check



## Damage Photos




1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint




3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsf  
Dented  
Over 2 UpTo 10mm



6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm

No Image



9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

12: Boot Lid  
Scratched  
Over 25mm Thru Paint

No Image




13: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

14: Wheel osr  
Scratched  
Over 50mm




15: Door osr  
Chipped  
1 To 5



16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Chipped  
1 To 5



18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Chipped  
1 To 5



20: Wheel osf  
Scratched  
Up To 50mm



21: Screen Front  
Chipped  
UpTo 10mm



22: Roof  
Chipped  
Edge Chip

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK