



# VEHICLE INSPECTION REPORT

**RA65ZZB**

## Renault Megane 1.5 dCi Dynamique Nav 5dr

**Non Runner**  
Inspection

Vehicle	
Serious Damage?	No
VAT	VAT Qualifying
V5	Present



### Details

Reg. date	29/01/2016	Body Style	Hatchback	Last service miles	65,560
Year	2016	Keys	2	MOT Due	Expired
Mileage	76,524 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	5	Doors	5
VIN	VF1BZ890H54372073	Last service date	22/09/2023		

CAMBELT + WATER PUMP REPLACED 05/01/2022 @ 58642 MILES Last service 22/09/2023 @ 65560 miles (5 MAIN DEALER SERVICES) SPANNER LIGHT ON DASH


### Tyres

NSF	ZEETEX	4.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	1.0mm
OSR	MICHELIN	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Dented  
With Paint Damage






3: Wing nsf  
Scratched  
Over 25mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsr  
Chipped  
1 To 5



8: Door nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
Over 30mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



14: Qtr Panel osr  
Poor Previous Repair  
Poor Paint





15: Wheel osr  
Scratched  
Up To 50mm



16: Door osr  
Dented  
Over 2 UpTo 10mm



17: Door osr  
Scratched  
Over 25mm Not Thru Paint




18: Door osf  
Dented  
With Paint Damage



19: Wing osf  
Dented  
With Paint Damage



20: Wheel osf  
Scratched  
Over 50mm



21: Sill os  
Dented  
With Paint Damage

22: Tyre osf  
Less Than 1.6mm  
Illegal

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK