



VEHICLE INSPECTION REPORT

RJ62ZWT

Renault Megane 1.5 dCi 110 Dynamique TomTom 5dr [Start Stop]

Cat: N Non Runner

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 Present

nama
GRADE
4

Details

Reg. date 27/02/2013

Year 2013

Mileage 150,000 Miles
Warranted

Fuel Type Diesel

Colour BLACK

VIN VF1BZ140647826615

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Number of stamps 4

Last service date 24/08/2022

Last service miles 123,789

MOT Due Expired

CAP Clean £640.00

CAP Average £260.00

CAP Below £200.00

Gearbox MANUAL

Gears 6

Doors 5

NON RUNNER Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair. Last service 24/08/2022 @ 123789 miles (4 MAIN DEALER SERVICES) EML LIGHT ON
SPANNER LIGHT ON
CHECK INJECTION SYSTEM DISPLAYS ON DASH
CHECK ANTI POLLUTION DISPLAYS ON DASH

Tyres

NSF WESTLAKE 4.0mm

NSR LAUFENN 3.0mm

OSF WESTLAKE 4.0mm

OSR BUDGET 3.0mm

Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Bumper Front Grill
Missing
Replace



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5

No Image



7: Wing nsf
Scratched
Over 25mm Not Thru Paint


8: Screen Front
Cracked
Replace



9: Door nsf
Dented
Over 30mm



10: Door nsr
Chipped
1 To 5



11: Door nsr
Scratched
Over 25mm Not Thru Paint




12: Qtr Panel nsr
Dented
Over 30mm



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Boot Lid
Poor Previous Repair
Poor Paint



16: Wheel osr
Scratched
Over 50mm




17: Qtr Panel osr
Chipped
1 To 5



18: Door osr
Dented
Between 10mm + 30mm



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Over 50mm



23: Door Mirror Assy osf
Broken
Replace



24: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK