



VEHICLE INSPECTION REPORT

YT69FJC

Hyundai I40 1.6 CRDi SE Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2019	Keys	2	CAP Clean	£5,500.00
Year	2019	Service history	Yes	CAP Average	£4,700.00
Mileage	70,863 Miles Warranted	Service documents	Service Book	CAP Below	£3,925.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	GREY	Last service date	10/04/2024	Gears	6
VIN	KMHLC81SLKU149549	Last service miles	63,270		
Body Style	Estate	MOT Due	16/09/2025		

£65 ADDITIONAL FEE. Last Service: 10/04/2024 at 63270 miles. (4 services)

Tyres

NSF	NEXEN	4.0mm
NSR	APOLLO	4.0mm
OSF	NEXEN	4.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
1 To 5




5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

9: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

10: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Dented
Over 2 UpTo 10mm



14: Door osf
Chipped
1 To 5

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK