



VEHICLE INSPECTION REPORT

ET66MTU

Toyota RAV4 2.5 VVT-i Hybrid Business Ed Plus TSS 5dr CVT 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/01/2017	Keys	2	CAP Clean	£12,000.00
Year	2017	Service history	Yes	CAP Average	£10,850.00
Mileage	51,024 Miles Warranted	Service documents	Service Book	CAP Below	£9,675.00
Fuel Type	Hybrid Electric	Number of stamps	8	Gearbox	CVT
Colour	RED	Last service date	04/11/2024	Gears	1
VIN	JTMWRREV50D028118	Last service miles	47,935		
Body Style	Estate	MOT Due	17/11/2025		

Last Service - 04.11.2024 at 47935 miles (8 MAIN DEALER SERVICES)

Tyres



NSF	BUDGET	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Over 50mm

No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Up To 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Poor Previous Repair
Paint Flake

No Image

No Image

11: Boot Lid
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
Over 2 UpTo 10mm



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK