



VEHICLE INSPECTION REPORT

LA60GFV

Renault Megane 1.6 16V I-Music 5dr

Imported
Inspection

Vehicle	
Serious Damage?	No
VAT	Margin
V5	Present



Details

Reg. date	01/09/2010	Keys	2	CAP Clean	£510.00
Year	2010	Service history	Yes	CAP Average	£220.00
Mileage	139,253 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	MANUAL
Colour	BLUE	Last service date	26/10/2023	Gears	5
VIN	VF1BZ0H0543845613	Last service miles	123,946	Doors	5
Body Style	Hatchback	MOT Due	03/11/2025		

IMPORTED. £100 ADDITIONAL FEE. Last service 26/10/2023 @ 123946 miles (8 SERVICES 1 MAIN DEALER)

Tyres

NSF	RAPID	4.0mm
NSR	BUDGET	3.0mm
OSF	RAPID	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Alloy wheels
- Radio/CD
- Front armrest
- Metallic Paint
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Wheel osr
Scratched
Over 50mm




13: Door osr
Chipped
1 To 5



14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Roof
Poor Previous Repair
Paint Flake



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK