



VEHICLE INSPECTION REPORT

BJ57ONU

Land Rover Freelander 2.2 Td4 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	25/09/2007	Body Style	Estate	MOT Due	25/08/2025
Year	2007	Keys	1	CAP Clean	£990.00
Mileage	140,504 Miles Warranted	Service history	Yes	CAP Average	£590.00
Fuel Type	Diesel	Service documents	Service Book	CAP Below	£275.00
Colour	BLACK	Number of stamps	11	Gearbox	MANUAL
VIN	SALFA27B68H060543	Last service date	20/08/2024	Gears	6

£65 ADDITIONAL FEE Last service 20/08/2024 @ 137450 miles (11 SERVICES 3 MAIN DEALER)

Tyres

NSF	BUDGET	4.0mm
NSR	MATADOR	2.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Cruise control
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Navigation system
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing osf
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips

No Image

4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Wheel nsf
Scratched
Over 50mm




7: Door nsf
Chipped
1 To 5

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
2 Or Less UpTo 10mm




10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Chipped
1 To 5



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image



15: Bumper Rear
Scratched
Over 25mm Not Thru Paint

16: Other
N/A
N/A



17: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




19: Wheel osr
Scratched
Over 50mm



20: Door osr
Chipped
1 To 5



21: Door osf
Chipped
1 To 5



22: Door osf
Scratched
Over 25mm Not Thru Paint



23: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		