



VEHICLE INSPECTION REPORT

GU10WKV

Honda Jazz 1.4 i-VTEC ES 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	30/03/2010	VIN	SHHGG6760AU008831	CAP Average	£1,800.00
Year	2010	Body Style	Hatchback	CAP Below	£1,350.00
Mileage	69,077 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	23/07/2025	Gears	5
Colour	RED	CAP Clean	£2,250.00	Doors	5

Last Service - 19.07.2024 at 64772 miles (12 services) Passenger rear window fault and rear brakes binding

Tyres

NSF	AVON	2.0mm
NSR	AVON	3.0mm
OSF	AVON	2.0mm
OSR	AVON	3.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Rear wiper
- Air conditioning
- Rear electric windows
- ABS
- Remote central locking
- Radio/CD
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Poor Previous Repair
Paint Flake

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsr
Chipped
1 To 5



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Dented
Over 30mm



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Chipped
1 To 5



18: Door osf
Dented
Over 2 UpTo 10mm



19: Wing osf
Dented
Over 30mm



20: Wheel osf
Scratched
Over 50mm



21: Roof
Poor Previous Repair
Paint Flake

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK