



VEHICLE INSPECTION REPORT

LB15FGP

Kia Rio 1.25 SR7 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date 31/07/2015

Year 2015

Mileage 101,616 Miles
Warranted

Fuel Type Petrol

Colour WHITE

VIN KNADN511LF6712436

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 1

Last service date 10/08/2016

Last service miles 17,750

MOT Due 31/01/2026

CAP Clean £2,575.00

CAP Average £2,100.00

CAP Below £1,625.00

Gearbox MANUAL

Gears 5

Doors 5

£100 ADDITIONAL FEE.

Last Service -10.08.2016 at 17750 miles (1 services)

Tyres

NSF BUDGET 3.0mm

NSR GOODYEAR 2.0mm

OSF ZEETEX 4.0mm

OSR BUDGET 4.0mm

Spare

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Dented
Hail - Moderate



2: D Pillars
Dented
2 Or Less Up To 10mm



3: Screen Front
Chipped
UpTo 10mm



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Cracked
UpTo 25mm



6: Wing nsf
Dented
With Paint Damage



7: Wheel nsf
Scratched
Over 50mm



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Cracked
Over 25mm



13: Reflector nsr
Broken
Replace



14: Boot Lid
Chipped
1 To 5

No Image



15: Wing osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm



17: Door osr
Rusted
Over 5mm



18: Door osf
Dented
Over 30mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK