



VEHICLE INSPECTION REPORT

LD10SEY

Toyota IQ 1.0 VVT-i 3dr

Cat: N

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date 24/03/2010

Year 2010

Mileage 140,076 Miles
Warranted

Fuel Type Petrol

Colour WHITE

VIN JTNML11080J050289

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Number of stamps 9

Last service date 08/02/2025

Last service miles 135,547

MOT Due 15/02/2026

CAP Clean £1,050.00

CAP Average £650.00

CAP Below £275.00

Gearbox MANUAL

Gears 5

Doors 3

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.

Last Service - 08.02.2025 at 135547 miles (9 MAIN DEALER SERVICES)

EML light on

Vsc off flashing on dash

Traction light on

Tyres

NSF DUNLOP 3.0mm

NSR NEXEN 5.0mm

OSF DUNLOP 3.0mm

OSR NEXEN 5.0mm

Spare

Features


- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos




1: Carpets Front
Holed
UpTo 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 25mm Not Thru Paint




5: Wheel nsf
Corroded
Light



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm




15: Door osf
Dented
Over 2 UpTo 10mm



16: Wing osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Up To 50mm



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Chipped
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK