



# VEHICLE INSPECTION REPORT

**GX13UJY**

## Citroen C3 Picasso 1.6 HDi 8V Selection 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
4

### Details

Reg. date 27/03/2013

Year 2013

Mileage 102,627 Miles  
Warranted

Fuel Type Diesel

Colour BLUE

VIN VF7SH9HP4DT509254

Body Style MPV

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 10

Last service date 26/09/2022

Last service miles 66,267

MOT Due 22/09/2025

CAP Clean £1,650.00

CAP Average £1,225.00

CAP Below £825.00

Gearbox MANUAL

Gears 5

Last Service - 26.09.2022 at 66267 miles (10 main dealer services) EML LIGHT ON

### Tyres

NSF BUDGET 4.0mm

NSR BUDGET 4.0mm

OSF BUDGET 3.0mm

OSR BUDGET 4.0mm

Spare

## Features


- Cruise control
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels
- Rear wiper
- Fixed panoramic glass roof
- Metallic Paint
- Central locking
- Radio/CD
- Air conditioning
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Chipped  
1 To 5

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Dented  
Over 30mm



14: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm






15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Chipped  
1 To 5



17: Door osr  
Scratched  
Over 25mm Not Thru Paint



18: Door osf  
Dented  
Over 30mm



19: Wheel osf  
Scratched  
Over 50mm



20: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK