



VEHICLE INSPECTION REPORT

VF64AOP

Nissan Juke 1.5 dCi Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/01/2015	Keys	2	CAP Clean	£2,600.00
Year	2015	Service history	Yes	CAP Average	£2,125.00
Mileage	103,211 Miles Warranted	Service documents	Service Book	CAP Below	£1,650.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	BLUE	Last service date	16/06/2021	Gears	5
VIN	SJNFCAF15U7087109	Last service miles	82,092	Doors	5
Body Style	Hatchback	MOT Due	04/08/2025		

£100 ADDITIONAL FEE Last service 16/06/2021 @ 82092 miles (1 SERVICE)

Tyres

NSF	CONTINENTAL	3.0mm
NSR	MICHELIN	3.0mm
OSF	BUDGET	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5

No Image



8: Door nsr
Dented
Over 30mm

7: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Door osr
Chipped
1 To 5

No Image



17: Door osr
Scratched
Over 25mm Not Thru Paint

18: Door osf
Chipped
1 To 5

No Image



19: Door osf
Scratched
Over 25mm Not Thru Paint

20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm

22: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK