



# VEHICLE INSPECTION REPORT

**GU65AAE**

## Vauxhall Mokka 1.6i SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	14/09/2015	Keys	1	CAP Clean	£3,050.00
Year	2015	Service history	Yes	CAP Average	£2,575.00
Mileage	71,011 Miles Warranted	Service documents	Service Book	CAP Below	£2,100.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	BROWN	Last service date	28/02/2025	Gears	5
VIN	W0LJD7EE3FB202817	Last service miles	70,133	Doors	5
Body Style	Hatchback	MOT Due	04/01/2026		

Last Service - 28.02.2025 at 70133 miles (6 services)

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Poor Previous Repair  
Poor Paint



8: Door nsr  
Chipped  
1 To 5

No Image



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Up To 50mm

No Image



11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

12: Bumper Rear  
Chipped  
Multiple Chips

No Image



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



15: Wheel osr  
Scratched  
Up To 50mm




16: Door osr  
Scratched  
Over 25mm Not Thru Paint




17: Door osf  
Chipped  
1 To 5



18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Scratched  
Over 25mm Not Thru Paint



20: Wing osf  
Scratched  
Over 25mm Not Thru Paint





21: Wheel osf  
Scratched  
Up To 50mm



22: Screen Front  
Chipped  
UpTo 10mm

**Interior**

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No