



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WO18TGF

BMW 2 Series 220d M Sport 2dr [Nav] Step Auto

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

nama
GRADE
3

Details

| | | | | | |
|------------|---------------------------|--------------------|------------|-------------|------------|
| Reg. date | 30/06/2018 | Keys | 2 | CAP Clean | £14,050.00 |
| Year | 2018 | Service history | Yes | CAP Average | £12,950.00 |
| Mileage | 29,545 Miles Warranted | Service documents | Printout | CAP Below | £11,800.00 |
| Fuel Type | Diesel | Number of stamps | 4 | Gearbox | AUTOMATIC |
| Colour | BLUE | Last service date | 28/04/2023 | Gears | 8 |
| VIN | WBA2U12040VD70323 | Last service miles | 21,098 | | |
| Body Style | Coupe | MOT Due | 29/06/2026 | | |

£65 ADDITIONAL FEE LAST SERVICE 28/4/23 @ 21098 MILES (4 SERVICE 3 MAIN DEALER) PRINT

Tyres

| | | |
|-------|-------------|-------|
| NSF | BRIDGESTONE | 4.0mm |
| NSR | BRIDGESTONE | 2.0mm |
| OSF | BUDGET | 4.0mm |
| OSR | BRIDGESTONE | 3.0mm |
| Spare | | |

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Navigation system
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel osr
Dented
Over 30mm



5: Wheel osr
Scratched
Over 50mm



6: Door osf
Dented
Over 2 UpTo 10mm

No Image



7: Door osf
Scratched
Over 25mm Not Thru Paint

8: Wing osf
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Bonnet
Chipped
1 To 5




11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Door nsf
Chipped
1 To 5



14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Wheel nsr
Scratched
Over 50mm



16: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |