



VEHICLE INSPECTION REPORT

OY11UTG

Vauxhall Zafira 1.8i Excite 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2011	Body Style	MPV	Last service miles	126,210
Year	2011	Keys	1	MOT Due	20/11/2025
Mileage	131,864 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	14		
VIN	W0LOAHM75B2081016	Last service date	15/11/2024		

£100 ADDITIONAL FEE

Clutch replaced 16.11.2023 @ 114490 miles

Cambelt + Water pump Replaced 19.11.2021 @ 94318 Miles

Last Service - 15.11.2024 at 126210 miles (14 services) Exhaust blowing

Tyres


NSF	FALKEN	2.0mm
NSR	BUDGET	3.0mm
OSF	FALKEN	Illegal
OSR	BUDGET	3.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Wheel nsf
Scratched
Over 50mm



7: Screen Front
Chipped
UpTo 10mm



8: Door nsf
Chipped
1 To 5

No Image

9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Door nsr
Chipped
1 To 5

No Image

11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Sill os
Rusted
UpTo 5mm



13: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

No Image

14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Wheel nsr
Scratched
Over 50mm



16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Boot Lid
Chipped
1 To 5



18: Qtr Panel osr
Dented
With Paint Damage



19: Wheel osr
Scratched
Over 50mm




20: Sill os
Chipped
Over 5mm



21: Door osr
Chipped
1 To 5

No Image

22: Door osr
Scratched
Over 25mm Not Thru Paint



23: Door osf
Chipped
1 To 5

No Image

24: Door osf
Scratched
Over 25mm Not Thru Paint



25: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



26: Wing osf
Chipped
1 To 5

No Image



27: Wing osf
Scratched
Over 25mm Not Thru Paint

28: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK