



VEHICLE INSPECTION REPORT

FY59WKO

BMW 5 Series 520d SE Business Edition 5dr Step Auto [177]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/10/2009	Body Style	Estate	MOT Due	08/11/2025
Year	2009	Keys	2	CAP Clean	£1,425.00
Mileage	146,902 Miles Warranted	Service history	Yes	CAP Average	£1,125.00
Fuel Type	Diesel	Number of stamps	12	CAP Below	£825.00
Colour	BLUE	Last service date	31/10/2022	Gearbox	AUTOMATIC
VIN	WBAPX32070C187192	Last service miles	122,509	Gears	6

Last Service: 31/10/2022 at 122509 miles. (12 services) 12 Services not all stamped . Lots of Bills

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Qtr Panel osr
Dented
Over 30mm



14: Door osr
Chipped
1 To 5

No Image



15: Door osr
Scratched
Over 25mm Not Thru Paint

16: Door osf
Dented
Over 2 UpTo 10mm



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: Wheel osr
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK