



VEHICLE INSPECTION REPORT

GV04MVM

Ford Focus 1.6 Edge 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/05/2004	VIN	WF0AXXGCD4R26172	Gearbox	MANUAL
Year	2004	Body Style	Hatchback	Gears	5
Mileage	159,230 Miles Warranted	Keys	2	Doors	5
Fuel Type	Petrol	Service history	None		
Colour	SILVER	MOT Due	09/07/2025		

£50 ADDITIONAL FEE.
NO SERVICE HISTORY High clutch


Tyres

NSF	LAUFENN	4.0mm
NSR	LAUFENN	4.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	4.0mm
Spare		

Features


- Rear wiper
- Front electric windows
- Passenger airbag
- Alloy wheels
- Radio/CD
- Metallic Paint
- Central locking
- Body coloured bumpers
- ABS
- Remote central locking
- Air conditioning
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
UpTo 25mm




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Rusted
Holed



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Sill ns
Rusted
Holed



9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Door nsr
Scratched
Over 25mm Not Thru Paint




11: Qtr Panel nsr
Rusted
UpTo 5mm



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Dented
Over 2 UpTo 10mm




16: Qtr Panel osr
Dented
Over 30mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 2 UpTo 10mm



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Dented
2 Or Less UpTo 10mm

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



23: Wing osf
Rusted
Over 5mm



24: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK