



VEHICLE INSPECTION REPORT

LR57NYS

Nissan Note 1.6 SVE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date 28/09/2007

Year 2007

Mileage 97,958 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN SJNFCAE11U1122664

Body Style MPV

Keys 2

Service history Yes

Service documents Printout

Number of stamps 8

Last service date 12/12/2023

Last service miles 82,809

MOT Due 08/01/2026

CAP Clean £810.00

CAP Average £410.00

CAP Below £200.00

Gearbox MANUAL

Gears 5

£100 ADDITIONAL FEE Last service 12/12/2023 @ 82809 miles (8 SERVICES 1 MAIN DEALER) High clutch

Tyres

NSF BUDGET 2.0mm

NSR BUDGET 3.0mm

OSF BUDGET 4.0mm

OSR BUDGET 3.0mm

Spare

Features


- Rear wiper
- Towbar
- Rear electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



12: Boot Lid
Dented
Over 30mm



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Dented
With Paint Damage



15: Door osr
Dented
Over 2 UpTo 10mm

16: Door osf
Dented
Over 30% Of Panel



17: Wing osf
Chipped
1 To 5

18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK